CERTIFICATE FITNESS

To be filled by the Inspecting Officer (Acet. Engineer)

Νt) (2/BS/VBP/2025-26 ch: 01	Dt. 23 - 01 - 1970) 08 2025
	1.	Name of the Officer	TOSE M.V
	2.	Name of the School	St. Ephrem Seminary Public School
	3.	Location with name of Education District/ Sub. District	vetikkal, Aluva/Kolenchery sub Dt.
	4.	Classification of Building as specified in column 4 of the application for fitness certificate and size.	Permanent Multistorial (v1+3), loor: 67.00×9.70×3.60(10 class rooms) 2015-40×9.70×3.60(2×2 class rooms)
			2x15.40x9.70x3.60(10 clas) rooms + Toile 2x15.40x9.70x3.60(2x2 class rooms) 2x15.40x9.70x3.60(10 class rooms + Toilets) 2x15.40x9.70x3.60(2x2 class room).
	5.	Period for which the certificate is issued 2025 - 2026.	2x15.40x9.70x3.60(2x2c)ass room).
	δ.	a) Foundation and basement b) Superstructure c) Doors and Windows	2x15.40x9.70x3.60(10 clas) rooms+Toiles 2x15.40x9.70x3.60(2x2 class rooms No.
		d) Wood work wrought and put up	
		e) Roof f) Flooring	12
		g) Miscellaneous (Cracks, etc.)	
	7.	Any major defects noticed which will render the building unsafe in any manner	No.
	8	Whether maintenance works have been done properly	Yes. Is sound under normal

Whether the structure is sound or not for conducting classes

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished exposured with this partificate. separately with this certificate.

CERTIFICATE

in an at the same inapported by the On	0).	08. 2023		and
certified that the school building was inspected by me on found to be fit / wnfit to conduct classes, for the period	25-	2026.	-11-	for the
found to be fit / unfit to conduct classes, for the period		2 2 2 4		-
reasons stated above.				

Place: Kolenchery Date: 01,08,2025



Assistant Executive Engineer LSGD Ssistent Engineeradavacone Block Panchayath, Kolenchery

500/8-6-13